


1&2 bedroom apartments





## 2 bedroom apartment

Plot 308 – as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 309 - as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor




Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.

## 2 bedroom apartment

Plot 310 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 311 – as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 312 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 313 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 1 bedroom apartment

Plot 314 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 315 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.

## 2 bedroom apartment

Plot 316 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 317 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 318 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 319 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 320 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 321 - as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 322 – as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 1 bedroom apartment

Plot 323 – as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.







Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


## 2 bedroom apartment

Plot 324 – as shown



This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.





Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.